

U.S. Officials Only

CONFIDENTIAL

CENTRAL INTELLIGENCE AGENCY

INFORMATION REPORT

25X1A

COUNTRY Paraguay

SUBJECT Description of Road from Asunción to Paraná River

PLACE ACQUIRED
(BY SOURCE)

DATE ACQUIRED
(BY SOURCE)

DATE (OF INFO.)

25X1X

URR NO.	
DAS NO.	
OCI NO.	

DATE DISTR. 11-MAY-54

NO. OF PAGES 2

3. National Geographic maps show a road running almost due east from Asunción to the Brazilian town of Foz de Iguaçu, but this road does not exist. We had a rough idea of the route to be followed to reach Hernandarias, and despite the urging of all who knew we contemplated the trip, we did not take a guide. Very little information regarding our proposed route could be obtained in Asunción. We carried ample supplies of food and camping equipment. Guns for protection as well as hunting were carried as we were told we might encounter bandits. Inasmuch as it was reported that no gasoline was available in the area where we were to travel, we carried three drums which contained about 120 gallons of gasoline.
4. Following is a detailed account of the trip. The figures given are in miles as the speedometers on the vehicles were in miles. Kilometers are given when marker posts were encountered.

U.S. Officials Only

CONFIDENTIAL

25X1A

DISTRIBUTION	STATE	ARMY	NAVY	AIR	FBI
--------------	-------	------	------	-----	-----

This report is for the use within the CIA or the Intelligence components of the Departments or Agencies indicated above. It is not to be transmitted overseas without the concurrence of the

CONFIDENTIAL/US OFFICIALS ONLY

25X1A

- 2 -

0. Start
2.6 Zero km marker in Asunción from which distances in Paraguay are computed.
- We left Asunción at 0500 1 Feb 53, and for the first 110 miles we followed the "Ruta" (I know of no other identification) which is one of the two main highways in Paraguay. The first 50 miles of road are of asphalt and would compare roughly to a secondary (state) road in the US.
25. Village of Ypacarai (Yipicaray)
36.7 Village of Caacupe
48.4 Village of Barrero Grande
49.3 End of the asphalt road and beginning of a gravel road which was fairly well maintained, about like a county road in the US.
- The land was gently rolling with an occasional small but fairly prominent hill. A fair portion of the land appeared to be under cultivation near Asunción. Land cultivation is done by such primitive means that it was difficult to determine whether land was cultivated or whether crops were growing wild. The amount of cultivated land decreases as one gets further away from Asunción. In this area most of the houses are of very primitive construction, usually consisting of one or two rooms with dirt floors, walls of poles plastered with mud, and thatched roofs. The roof usually extends beyond the house on one side to provide a shelter for outdoor cooking. Some houses had adobe walls in place of plastered poles. Invariably there was a beehive- or dome-shaped oven about three feet in diameter in the backyard. (See photos 1 and 2).
- 67.0 Village of San José, population about 100. There is a small military post here.
74.2 Marker, 113 kms.
75.4 Stream.
77.6 Stream, flowing north.
81. Trail to left (to Caraguatay?).
83.3 Trail to right (to Coronel Martínez?).
86.2 Junction just south of Coronel Oviedo, turn right.
91.3 Marker, 140 kms.
95.9 Estancia La Candelaria on right.
98.7 Río Ibicuary (spl?), 70 feet wide, crossed by a good highway bridge.
- 103.1 Road to right to Villarrica via Yataity).
107. Village of Mbocayaty (Mbocayatih).
- Mbocayaty has a population of about 200 and is laid out with a rectangular street plan. The streets are about 75 feet wide from building line to building line. Traffic must go through the town and it would be difficult to go around it.
- Side trip to Villarrica south of Mbocayaty.
- 108.8 Agriculture experiment station on left.
109.4 Stream.
111. Villarrica, a fair-sized town where we replenished our gasoline supply. It has streets laid out in a rectangular pattern, and they are surfaced. It is the headquarters and supply center for the eastern area, 800 to one thousand population.
107. Leave Mbocayaty, going east.
108.5 Small stream, draining to northwest (Arroyo Doña Gervacia?).
110.5 Round hill, 100 feet above road level, 300 yards to right.

CONFIDENTIAL/US OFFICIALS ONLY

CONFIDENTIAL/US OFFICIALS ONLY

25X1A

- 3 -

- 110.9 Junction; the main gravel road continues eastward. The road to Hernandarias turns northeastward and is a dirt road with some grading. It is used quite frequently by three-ton trucks which go as far as Caaguazú. Houses are very infrequent after leaving Mboacaty.
- 115.8 Village on left.
- 117.2 Rio Tebicuary, 50 feet wide, flowing west. It is crossed by a fairly good wooden bridge supported on wooden piles.
- 119.5 Village Coronel Troche, entering forest area.
- 126.2 Stream, draining east; logging operation.
- 143.5 Village of Caaguazú. Graded road ends. Entering range land area, mostly open grassland with small forested areas. From here the road deteriorates to a mere trail and in the open range land, it is merely deep ruts worn by high-wheeled ox carts. The jeep became stuck many times on the high center of the road and had to be pulled off by winch and cable to a spot where its wheels could again grip the ground. Through the forest areas the trees had been cleared enough to allow the passage of one vehicle (see Photo 3). There were many mudholes where rain water stands continuously, and it was necessary to winch the vehicles through these places. Numerous small streams were encountered and the only bridges consisted of two half logs laid parallel across the streams and spaced to fit the wheels.
- 153.2 Instituto Geografico Militar (IGM) Monument # W27-PF-6 on right side of road. It is a four-inch bronze tablet set in a concrete post eight inches square and eight inches high.
- 154.2 Small stream, drains east.
- 156.8 Small stream, drains east.
- 161.2 Junction, turn right.
- 164.9 Creek, drains east.
- 165.4 IGM Monument # W27-PF-12 on left side of road.
- 169.3 Enter timber.
- 170.4 Leave timber.
- 171.1 Creek, drains east, crossed by a small inclined trestle wooden bridge in poor condition.
- 171.3 IGM Monument on right at cattle corral.
177. Rio Ytu, 20 feet wide, drains east. It is crossed by a very poor log bridge which is falling apart.
- 177.9 Junction, road (to San Joaquin ?) enters from right.
- 178.2 Village of Ytu, population about 50. There is a hotel, a small "hospital" and facilities for radio communication here. We arrived here about 1800, the major portion of the day having been spent traversing the last 35 miles. We went to the military post and presented a letter we had obtained from the General Staff of the Paraguayan Army requesting the extension of courtesies to us by military men. An armed soldier guard was posted over our camp which we located in a vacant space across the road from the military post.
- We departed from Ytu at 0630. The road for the next 70 miles took us through some of the best range land we had seen in Paraguay. It was gently rolling grassland with some small areas of forest. There appeared to be good forage, but we saw surprisingly few cattle. The area is very sparsely settled with only an occasional ranch house. Villagers in Ytu told us there were rumors of bandits and cattle rustlers in this area.
183. Estancia Laguna Vera, owned by Emilio Langfahn who was very friendly and invited us to stop and visit. The estancia has 5,625 hectares and 400 head of cattle including some Zebu cattle imported from Brazil.

CONFIDENTIAL/US OFFICIALS ONLY

CONFIDENTIAL/US OFFICIALS ONLY

25X1A

- 4 -

- 184.7 Swamp with quicksand, crossed by 300 feet of log corduroy road.
 185.1 Swamp with thick gumbo-like mud, crossed by 250 feet of corduroy road. Very rough and hard to cross.
 185.4 Stream, 25 feet wide, drains east.
 186. Shacks. (See Photo 4)
 187. Enter timber.
 189.2 Dense woods. Swamp of about 100 acres area, 100 yards to left.
 198.2 Small clearing with corduroy road.
 198.7 Clearing with swamp which is crossed by a corduroy road. Small house to right of clearing.
 199.3 Stream, drains east.
 203.9 Clearing with house on right, road very bad with many mudholes, enter timber.
 209.9 Clearing, road better.
 211.3 Estancia Bella Vista; it has a number of old buildings scattered around a clearing. (See Photo 5)
 214.9 Swamp crossed by corduroy road.
 215.8 Stream, drains southeast, log loading area. (See Photos 6 - 11)
 216.1 Gate and road junction, turn right.
 218.6 Road to left.
 220.2 Looking southwest over plain. (See Photo 12)
 222.7 Gate in fence running east-west. (See Photo 13)
 223.3 Gate in fence and canal running east-west.
 225.7 Gate in fence running northeast-southeast.
 226.1 Gate to Estancia Los Palermos, house on left. (See Photo 14). This estancia is at the end of the telephone line from Hernandarias and has a telephone. A line of telephone poles parallels the road eastward. (See Photo 15)
 229.1 Gate in fence running northwest-southeast.
 232.3 Stream, three feet wide, drains west.
 232.4 Stream, two feet wide, drains west, crossed by a poor bridge.
 235. Enter timber.
 240. Leave timber.
 240.6 Acaray River, 50 feet wide, flows southeast, good bridge.
 242. Enter timber.
 244.5 Stream, three feet wide, flows south, crossed by a good wooden bridge 30 feet long with a very long approach. Stream runs very wide and is full in the rainy season. Beginning of poorly graded road on east side of bridge.
 245.7 Stream, two feet wide, flows south, crossed by a good bridge 30 feet long.
 248.9 Stream, 15 feet wide, flows south.
 249.7 Stream, three feet wide.
 254.3 Village of Itaguary has a military post (See Photo 16) and a small airfield. Beginning of fair road which is used for hauling yerba mate in trucks and ox carts. (See Photo 17)
 254.6 Acaray River, 20 feet wide, flows south.
 261.8 Stream, 10 feet wide, flows south.
 263. Two small bridges over small streams.
 264. Two small bridges over small streams.
 270.1 Stream flows southwest.
 273.1 Stream flows southwest.
 276.8 Stream flows southwest.
 276.9 Stream flows southwest.
 285.8 Stream 25 feet wide, flows southwest.
 288.2 Leave timber.
 290.2 Enter timber.
 297.7 Leave timber.
 308.2 Village of Hernandarias (See Photos 18 - 20). We arrived about 2100. There is a small hotel but the mayor of the village suggested that we camp in his lot where there was less chance of pilferage of our equipment.

CONFIDENTIAL/US OFFICIALS ONLY

CONFIDENTIAL/US OFFICIALS ONLY

25X1A

- 5 -

5. We intended ferrying our vehicles across the Acaray River to the village of Presidente Franco where new roads were to be built to serve a proposed colony of displaced Europeans. We found that a barge would have to be constructed to carry the trucks so rather than wait we hired a small boat to take us to Puerto Tacurupucu, about five miles down the river.
6. At Puerto Tacurupucu, which is a port of entry for Paraguay, there is an extremely dilapidated hand-operated marine railway for small boats. (See Photo 21)
7. We crossed the Paraná River here to the Brazilian side at Porto Bella Vista and then secured transportation by wagon to Foz de Iguaçu 17 miles downstream. We then crossed the Iguazú River into Argentina to the town of Eva Perón from where we took a taxi to the Argentine hotel at Iguazú Falls. The Argentine authorities held our passports while we visited the falls and instructed us not to take any pictures of the town of Eva Perón.
8. To return we went back to Eva Perón where we engaged a motor launch to take us up the river to Puerto Tacurupucu. At its junction with the Río Iguazú, the Río Paraná is about two thousand feet wide. It is very fast flowing and the banks slope back at 30 to 45 degrees to a height of about 200 feet above the river. (See Photos 22 - 24). Just above the junction of the Río Paraná and the Río Acaray, the two rivers come within 70 feet of each other and at this point (See Photo 25) the level of the Río Acaray is 100 feet below that of the Paraná. According to the map (USAF Preliminary Base, 1314-A, Villarrica), there is a village at the north end of this narrow strip but this village is actually only a couple of small shacks.
9. When we arrived back at Hernandarias, a small plane arrived from Asunción and we chartered it in order to fly over Presidente Franco, and thence westerly along the road between the Acaray and Monday Rivers. This road winds through the timber for about 60 kms and our flight carried us about 75 kms west of Presidente Franco. This area is gently rolling land and is all heavily forested (See Photos 26 - 30). If the soil is satisfactory the area could probably be developed into good agricultural land when the forest is cleared.
10. The Paraguayan Government has plans to create a road from Coronel Oviedo via Caaguazú to the Paraná River at its junction with the Iguazú River. This projected road would run in almost a straight line east and west and would serve as the communication link for a number of colonies to be established in the area. I do not believe the government intends to appropriate any money for the construction of this road, but it intends to rely upon future colonists in the area to construct it. In view of this I doubt that such a road will ever be constructed.

- end -

LIBRARY SUBJECT AND AREA CODES

154.2	2-
62.10	2-

CONFIDENTIAL/US OFFICIALS ONLY

To file with report.

25X1A



Unaccessioned work prints -

14 accessioned - CIA-121093-121106



1. AREA OF INTEREST		2. DATE	
3. AREA CAMP	4. LOCATION	5. REGION	6. DATE
7. DESCRIPTION OF AREA		8. COMMENTS	
(29) Area west of Hernandez wp			
9. DATE OF PHOTO		10. PHOTOGRAPH	
11. CLASSIFICATION			
12. CAPTIONED BY		13. DATE	
FORM 100 SEP 1948 60-53		CAPTION REPORT	




CIA PHOTO ACCESSION NO.		LOT NO.		DATE
AREA NAME NO.	COUNTRY	PROVINCE	PLACE	
GEOGRAPHIC COORDINATES		MAP REFERENCE		
TITLE				
(2) Farm house				
work print				
DATE OF PICTURE		SOURCE OF PICTURE		
CLASSIFICATION				
CAPTIONED BY		VERIFIED BY		
FORM NO. 80-83 SEP 1948				
CAPTION REPORT				



CIA PHOTO ACCESSION NO.		LOT NO.		DATE	
AREA (AMS NO.)		COUNTRY		PROVINCE	
				PLACE	
GEOGRAPHIC COORDINATES				MAP REFERENCE	
TITLE					
(C) Road through woods west of Bella Vista Estancia					
work print					
DATE OF PICTURE		SOURCE OF PICTURE			
CLASSIFICATION					
CAPTIONED BY				VERIFIED BY	
FORM NO. 60-83 SEP 1948					
CAPTION REPORT					




CIA (PHOTO ACCESSION NO.)		LOT NO.		DATE	
AREA (AMS NO.)		COUNTRY		PROVINCE	
				PLACE	
GEOGRAPHIC COORDINATES				MAP REFERENCE	
TITLE					
(5) Estancia Bella Vista building					
work print					
DATE OF PICTURE		SOURCE OF PICTURE			
CLASSIFICATION					
CAPTIONED BY				VERIFIED BY	
FORM NO. 10-53 SEP 1948					
CAPTION REPORT					




CIA PHOTO ACCESSION NO.		LOT NO.		DATE	
AREA (AMS NO.)		COUNTRY		PROVINCE	
				PLACE	
GEOGRAPHIC COORDINATES				MAP REFERENCE	
TITLE:					
(6) logging operations					
work permit					
DATE OF PICTURE		SOURCE OF PICTURE			
CLASSIFICATION					
CAPTIONED BY				VERIFIED BY	
FORM NO. 80-83 SEP 1948					
CAPTION REPORT					




CIA PHOTO ACCESSION NO.		LOT NO.		DATE	
AREA (AMS NO.)		COUNTRY		PROVINCE	PLACE
GEOGRAPHIC COORDINATES				MAP REFERENCE	
TITLE: (8) Logging operation					
DATE OF PICTURE		SOURCE OF PICTURE			
CLASSIFICATION					
CAPTIONED BY				VERIFIED BY	
FORM NO. 60-83 SEP 1948					
CAPTION REPORT					




CIA PHOTO ACCESSION NO.		LOT NO.		DATE	
AREA (AMS NO.)		COUNTRY		STATE	
GEOGRAPHIC COORDINATES				MAP REFERENCE	
TITLE					
(9) Logging operations					
wp					
DATE OF PICTURE		SOURCE OF PICTURE			
CLASSIFICATION					
CAPTIONED BY				VERIFIED BY	
FORM NO. 80-83 SEP 1948					
CAPTION REPORT					



CIA PHOTO ACCESSION NO.		LOT NO.		DATE	
AREA (AMS NO.)		COUNTRY		PROVINCE	
				PLACE	
GEOGRAPHIC COORDINATES				MAP REFERENCE	
TITLE					
(11) logging operations					
wp.					
DATE OF PICTURE		SOURCE OF PICTURE			
CLASSIFICATION					
CAPTIONED BY				VERIFIED BY	
FORM NO. 80-83 SEP 1948				CAPTION REPORT	



CIA PHOTO ACCESSION NO.		LOT NO.		DATE	
AREA NAME NO.		COUNTRY	PROVINCE	PLACE	
GEOGRAPHIC COORDINATES			MAP REFERENCE		
TITLE					
(12) Ant hills on plain at 2,200 miles					
wp					
DATE OF PICTURE		SOURCE OF PICTURE			
CLASSIFICATION					
CAPTIONED BY			VERIFIED BY		
FORM NO. 80-83 SEP 1948					
CAPTION REPORT					




CIA PHOTO ACCESSION NO.		LOT NO.		DATE	
AREA (AMS NO.)		COUNTRY		PROVINCE	
				PLACE	
GEOGRAPHIC COORDINATES				MAG. REFERENCE	
TITLE					
(20) Survey markers at corner of a					
building lot in Hernandezias					
wp					
DATE OF PICTURE		SOURCE OF PICTURE			
CLASSIFICATION					
CAPTIONED BY			VERIFIED BY		
FORM NO. 40-53 SEP 1948		CAPTION REPORT			




1. AGENCY ACQUISITION NO.		2. DATE	
3. AREA	4. COUNTRY	5. SUBJECT	6. DATE
7. DISPOSITION		8. COMMENTS	
<p>(23) Parana River bank</p> <p>up</p>			
9. DATE OF REPORT		10. REPORT NO.	
11. CLASSIFICATION			
12. APPROVAL		13. DISTRIBUTION	
<p>FORM NO. 66-53 SEP 1946</p> <p>CAPTION REPORT</p>			




1. TITLE		2. DATE	
3. AREA	4. SUBJECT	5. OBJECT	6. TYPE
7. DESCRIPTION		8. COMMENTS	
(24) Parama River bank wp			
9. DATE OF PHOTOGRAPH		10. PHOTOGRAPHER	
11. LOCATION		12. COORDINATES	
13. AIRCRAFT		14. WEAPON	
15. CAPTION REPORT			




DATE OF OBSERVATION		LOCATION		TIME	
NO.		CLASSIFICATION		REMARKS	
<p>(26) Clearing about 40 kms west of Herandarias from plane. on flight over Presidente Franco along road bet Acaray + Monday Rivers.</p>					
DATE OF REPORT		BY			
CLASSIFICATION		<p><i>Wp</i></p>			
CAPTIONED BY		<p><i>Kadey</i></p>			
FORM NO. 60-53 SEP 1948		CAPTION REPORT			



1. PHOTO ACQUISITION		2. LOCATION		3. DATE	
4. AREA		5. SUBJECT		6. REF.	
7. PHOTOGRAPHIC DATA		8. FILM		9. DEVELOPER	
<p>(27) Area west of Hernandezias</p> <p>Wp</p>					
10. DATE OF PHOTO		11. PHOTOGRAPHER			
12. CAMERA		13. LENS			
14. FILM		15. DEVELOPER			
16. DATE OF DEVELOPMENT		17. DEVELOPER			
18. DATE OF PRINTING		19. PRINTING			
20. DATE OF DISTRIBUTION		21. DISTRIBUTION			
22. DATE OF REVIEW		23. REVIEW			
24. DATE OF ARCHIVAL		25. ARCHIVAL			
26. DATE OF DESTRUCTION		27. DESTRUCTION			
28. DATE OF RECOVERY		29. RECOVERY			
30. DATE OF REPAIR		31. REPAIR			
32. DATE OF REPLACEMENT		33. REPLACEMENT			
34. DATE OF REMOVAL		35. REMOVAL			
36. DATE OF REUSE		37. REUSE			
38. DATE OF REPAIR		39. REPAIR			
40. DATE OF REPLACEMENT		41. REPLACEMENT			
42. DATE OF REMOVAL		43. REMOVAL			
44. DATE OF REUSE		45. REUSE			
46. DATE OF REPAIR		47. REPAIR			
48. DATE OF REPLACEMENT		49. REPLACEMENT			
50. DATE OF REMOVAL		51. REMOVAL			
52. DATE OF REUSE		53. REUSE			
54. DATE OF REPAIR		55. REPAIR			
56. DATE OF REPLACEMENT		57. REPLACEMENT			
58. DATE OF REMOVAL		59. REMOVAL			
60. DATE OF REUSE		61. REUSE			
62. DATE OF REPAIR		63. REPAIR			
64. DATE OF REPLACEMENT		65. REPLACEMENT			
66. DATE OF REMOVAL		67. REMOVAL			
68. DATE OF REUSE		69. REUSE			
70. DATE OF REPAIR		71. REPAIR			
72. DATE OF REPLACEMENT		73. REPLACEMENT			
74. DATE OF REMOVAL		75. REMOVAL			
76. DATE OF REUSE		77. REUSE			
78. DATE OF REPAIR		79. REPAIR			
80. DATE OF REPLACEMENT		81. REPLACEMENT			
82. DATE OF REMOVAL		83. REMOVAL			
84. DATE OF REUSE		85. REUSE			
86. DATE OF REPAIR		87. REPAIR			
88. DATE OF REPLACEMENT		89. REPLACEMENT			
90. DATE OF REMOVAL		91. REMOVAL			
92. DATE OF REUSE		93. REUSE			
94. DATE OF REPAIR		95. REPAIR			
96. DATE OF REPLACEMENT		97. REPLACEMENT			
98. DATE OF REMOVAL		99. REMOVAL			
100. DATE OF REUSE		101. REUSE			
102. DATE OF REPAIR		103. REPAIR			
104. DATE OF REPLACEMENT		105. REPLACEMENT			
106. DATE OF REMOVAL		107. REMOVAL			
108. DATE OF REUSE		109. REUSE			
110. DATE OF REPAIR		111. REPAIR			
112. DATE OF REPLACEMENT		113. REPLACEMENT			
114. DATE OF REMOVAL		115. REMOVAL			
116. DATE OF REUSE		117. REUSE			
118. DATE OF REPAIR		119. REPAIR			
120. DATE OF REPLACEMENT		121. REPLACEMENT			
122. DATE OF REMOVAL		123. REMOVAL			
124. DATE OF REUSE		125. REUSE			
126. DATE OF REPAIR		127. REPAIR			
128. DATE OF REPLACEMENT		129. REPLACEMENT			
130. DATE OF REMOVAL		131. REMOVAL			
132. DATE OF REUSE		133. REUSE			
134. DATE OF REPAIR		135. REPAIR			
136. DATE OF REPLACEMENT		137. REPLACEMENT			
138. DATE OF REMOVAL		139. REMOVAL			
140. DATE OF REUSE		141. REUSE			
142. DATE OF REPAIR		143. REPAIR			
144. DATE OF REPLACEMENT		145. REPLACEMENT			
146. DATE OF REMOVAL		147. REMOVAL			
148. DATE OF REUSE		149. REUSE			
150. DATE OF REPAIR		151. REPAIR			
152. DATE OF REPLACEMENT		153. REPLACEMENT			
154. DATE OF REMOVAL		155. REMOVAL			
156. DATE OF REUSE		157. REUSE			
158. DATE OF REPAIR		159. REPAIR			
160. DATE OF REPLACEMENT		161. REPLACEMENT			
162. DATE OF REMOVAL		163. REMOVAL			
164. DATE OF REUSE		165. REUSE			
166. DATE OF REPAIR		167. REPAIR			
168. DATE OF REPLACEMENT		169. REPLACEMENT			
170. DATE OF REMOVAL		171. REMOVAL			
172. DATE OF REUSE		173. REUSE			
174. DATE OF REPAIR		175. REPAIR			
176. DATE OF REPLACEMENT		177. REPLACEMENT			
178. DATE OF REMOVAL		179. REMOVAL			
180. DATE OF REUSE		181. REUSE			
182. DATE OF REPAIR		183. REPAIR			
184. DATE OF REPLACEMENT		185. REPLACEMENT			
186. DATE OF REMOVAL		187. REMOVAL			
188. DATE OF REUSE		189. REUSE			
190. DATE OF REPAIR		191. REPAIR			
192. DATE OF REPLACEMENT		193. REPLACEMENT			
194. DATE OF REMOVAL		195. REMOVAL			
196. DATE OF REUSE		197. REUSE			
198. DATE OF REPAIR		199. REPAIR			
200. DATE OF REPLACEMENT		201. REPLACEMENT			
202. DATE OF REMOVAL		203. REMOVAL			
204. DATE OF REUSE		205. REUSE			
206. DATE OF REPAIR		207. REPAIR			
208. DATE OF REPLACEMENT		209. REPLACEMENT			
210. DATE OF REMOVAL		211. REMOVAL			
212. DATE OF REUSE		213. REUSE			
214. DATE OF REPAIR		215. REPAIR			
216. DATE OF REPLACEMENT		217. REPLACEMENT			
218. DATE OF REMOVAL		219. REMOVAL			
220. DATE OF REUSE		221. REUSE			
222. DATE OF REPAIR		223. REPAIR			
224. DATE OF REPLACEMENT		225. REPLACEMENT			
226. DATE OF REMOVAL		227. REMOVAL			
228. DATE OF REUSE		229. REUSE			
230. DATE OF REPAIR		231. REPAIR			
232. DATE OF REPLACEMENT		233. REPLACEMENT			
234. DATE OF REMOVAL		235. REMOVAL			
236. DATE OF REUSE		237. REUSE			
238. DATE OF REPAIR		239. REPAIR			
240. DATE OF REPLACEMENT		241. REPLACEMENT			
242. DATE OF REMOVAL		243. REMOVAL			
244. DATE OF REUSE		245. REUSE			
246. DATE OF REPAIR		247. REPAIR			
248. DATE OF REPLACEMENT		249. REPLACEMENT			
250. DATE OF REMOVAL		251. REMOVAL			
252. DATE OF REUSE		253. REUSE			
254. DATE OF REPAIR		255. REPAIR			
256. DATE OF REPLACEMENT		257. REPLACEMENT			
258. DATE OF REMOVAL		259. REMOVAL			
260. DATE OF REUSE		261. REUSE			
262. DATE OF REPAIR		263. REPAIR			
264. DATE OF REPLACEMENT		265. REPLACEMENT			
266. DATE OF REMOVAL		267. REMOVAL			
268. DATE OF REUSE		269. REUSE			
270. DATE OF REPAIR		271. REPAIR			
272. DATE OF REPLACEMENT		273. REPLACEMENT			
274. DATE OF REMOVAL		275. REMOVAL			
276. DATE OF REUSE		277. REUSE			
278. DATE OF REPAIR		279. REPAIR			
280. DATE OF REPLACEMENT		281. REPLACEMENT			
282. DATE OF REMOVAL		283. REMOVAL			
284. DATE OF REUSE		285. REUSE			
286. DATE OF REPAIR		287. REPAIR			
288. DATE OF REPLACEMENT		289. REPLACEMENT			
290. DATE OF REMOVAL		291. REMOVAL			
292. DATE OF REUSE		293. REUSE			
294. DATE OF REPAIR		295. REPAIR			
296. DATE OF REPLACEMENT		297. REPLACEMENT			
298. DATE OF REMOVAL		299. REMOVAL			
300. DATE OF REUSE		301. REUSE			
302. DATE OF REPAIR		303. REPAIR			
304. DATE OF REPLACEMENT		305. REPLACEMENT			
306. DATE OF REMOVAL		307. REMOVAL			
308. DATE OF REUSE		309. REUSE			
310. DATE OF REPAIR		311. REPAIR			
312. DATE OF REPLACEMENT		313. REPLACEMENT			
314. DATE OF REMOVAL		315. REMOVAL			
316. DATE OF REUSE		317. REUSE			
318. DATE OF REPAIR		319. REPAIR			
320. DATE OF REPLACEMENT		321. REPLACEMENT			
322. DATE OF REMOVAL		323. REMOVAL			
324. DATE OF REUSE		325. REUSE			
326. DATE OF REPAIR		327. REPAIR			
328. DATE OF REPLACEMENT		329. REPLACEMENT			
330. DATE OF REMOVAL		331. REMOVAL			
332. DATE OF REUSE		333. REUSE			
334. DATE OF REPAIR		335. REPAIR			
336. DATE OF REPLACEMENT		337. REPLACEMENT			
338. DATE OF REMOVAL		339. REMOVAL			
340. DATE OF REUSE		341. REUSE			
342. DATE OF REPAIR		343. REPAIR			
344. DATE OF REPLACEMENT		345. REPLACEMENT			
346. DATE OF REMOVAL		347. REMOVAL			
348. DATE OF REUSE		349. REUSE			
350. DATE OF REPAIR		351. REPAIR			
352. DATE OF REPLACEMENT		353. REPLACEMENT			
354. DATE OF REMOVAL		355. REMOVAL			
356. DATE OF REUSE		357. REUSE			
358. DATE OF REPAIR		359. REPAIR			
360. DATE OF REPLACEMENT		361. REPLACEMENT			
362. DATE OF REMOVAL		363. REMOVAL			
364. DATE OF REUSE		365. REUSE			
366. DATE OF REPAIR		367. REPAIR			
368. DATE OF REPLACEMENT		369. REPLACEMENT			
370. DATE OF REMOVAL		371. REMOVAL			
372. DATE OF REUSE		373. REUSE			
374. DATE OF REPAIR		375. REPAIR			
376. DATE OF REPLACEMENT		377. REPLACEMENT			
378. DATE OF REMOVAL		379. REMOVAL			
380. DATE OF REUSE		381. REUSE			
382. DATE OF REPAIR		383. REPAIR			
384. DATE OF REPLACEMENT		385. REPLACEMENT			
386. DATE OF REMOVAL		387. REMOVAL			
388. DATE OF REUSE		389. REUSE			
390. DATE OF REPAIR		391. REPAIR			
392. DATE OF REPLACEMENT		393. REPLACEMENT			
394. DATE OF REMOVAL		395. REMOVAL			
396. DATE OF REUSE		397. REUSE			
398. DATE OF REPAIR		399. REPAIR			
400. DATE OF REPLACEMENT		401. REPLACEMENT			
402. DATE OF REMOVAL		403. REMOVAL			
404. DATE OF REUSE		405. REUSE			
406. DATE OF REPAIR		407. REPAIR			
408. DATE OF REPLACEMENT		409. REPLACEMENT			
410. DATE OF REMOVAL		411. REMOVAL			
412. DATE OF REUSE		413. REUSE			
414. DATE OF REPAIR		415. REPAIR			
416. DATE OF REPLACEMENT		417. REPLACEMENT			
418. DATE OF REMOVAL		419. REMOVAL			
420. DATE OF REUSE		421. REUSE			
422. DATE OF REPAIR		423. REPAIR			
424. DATE OF REPLACEMENT		425. REPLACEMENT			
426. DATE OF REMOVAL		427. REMOVAL			
428. DATE OF REUSE		429. REUSE			
430. DATE OF REPAIR		431. REPAIR			
432. DATE OF REPLACEMENT		433. REPLACEMENT			
434. DATE OF REMOVAL		435. REMOVAL			
436. DATE OF REUSE		437. REUSE			
438. DATE OF REPAIR		439. REPAIR			
440. DATE OF REPLACEMENT		441. REPLACEMENT			
442. DATE OF REMOVAL		443. REMOVAL			
444. DATE OF REUSE		445. REUSE			
446. DATE OF REPAIR		447. REPAIR			
448. DATE OF REPLACEMENT		449. REPLACEMENT			
450. DATE OF REMOVAL		451. REMOVAL			
452. DATE OF REUSE		453. REUSE			
454. DATE OF REPAIR		455. REPAIR			
456. DATE OF REPLACEMENT		457. REPLACEMENT			
458. DATE OF REMOVAL		459. REMOVAL			
460. DATE OF REUSE		461. REUSE			
462. DATE OF REPAIR		463. REPAIR			
464. DATE OF REPLACEMENT		465. REPLACEMENT			
466. DATE OF REMOVAL		467. REMOVAL			
468. DATE OF REUSE		469. REUSE			
470. DATE OF REPAIR		471. REPAIR			
472. DATE OF REPLACEMENT		473. REPLACEMENT			
474. DATE OF REMOVAL		475. REMOVAL			
476. DATE OF REUSE		477. REUSE			
478. DATE OF REPAIR		479. REPAIR			
480. DATE OF REPLACEMENT		481. REPLACEMENT			
482. DATE OF REMOVAL		483. REMOVAL			
484. DATE OF REUSE		485. REUSE			
486. DATE OF REPAIR		487. REPAIR			
488. DATE OF REPLACEMENT		489. REPLACEMENT			
490. DATE OF REMOVAL		491. REMOVAL			
492. DATE OF REUSE		493. REUSE			
494. DATE OF REPAIR		495. REPAIR			
496. DATE OF REPLACEMENT		497. REPLACEMENT			
498. DATE OF REMOVAL		499. REMOVAL			
500. DATE OF REUSE		501. REUSE			
502. DATE OF REPAIR		503. REPAIR			
504. DATE OF REPLACEMENT		505. REPLACEMENT			
506. DATE OF REMOVAL		507. REMOVAL			
508. DATE OF REUSE		509. REUSE			
510. DATE OF REPAIR		511. REPAIR			
512. DATE OF REPLACEMENT		513. REPLACEMENT			
514. DATE OF REMOVAL		515. REMOVAL			
516. DATE OF REUSE		517. REUSE			
518. DATE OF REPAIR		519. REPAIR			
520. DATE OF REPLACEMENT		521. REPLACEMENT			
522. DATE OF REMOVAL		523. REMOVAL			
524. DATE OF REUSE		525. REUSE			
526. DATE OF REPAIR		527. REPAIR			
528. DATE OF REPLACEMENT		529. REPLACEMENT			
530. DATE OF REMOVAL		531. REMOVAL			
532. DATE OF REUSE		533. REUSE			
534. DATE OF REPAIR		535. REPAIR			
536. DATE OF REPLACEMENT		537. REPLACEMENT			
538. DATE OF REMOVAL		539. REMOVAL			
540. DATE OF REUSE		541. REUSE			
542. DATE OF REPAIR		543. REPAIR			
544. DATE OF REPLACEMENT		545. REPLACEMENT			
546. DATE OF REMOVAL		547. REMOVAL			
548. DATE OF REUSE		549. REUSE			
550. DATE OF REPAIR		551. REPAIR			
552. DATE OF REPLACEMENT		553. REPLACEMENT			
554. DATE OF REMOVAL		555. REMOVAL			
556. DATE OF REUSE		557. REUSE			
558. DATE OF REPAIR		559. REPAIR			
560. DATE OF REPLACEMENT		561. REPLACEMENT			
562. DATE OF REMOVAL		563. REMOVAL			
564. DATE OF REUSE		565. REUSE			
566. DATE OF REPAIR		567. REPAIR			
568. DATE OF REPLACEMENT		569. REPLACEMENT			
570. DATE OF REMOVAL		571. REMOVAL			
572. DATE OF REUSE		573. REUSE			
574. DATE OF REPAIR		575. REPAIR			
576. DATE OF REPLACEMENT		577. REPLACEMENT			
578. DATE OF REMOVAL		579. REMOVAL			
580. DATE OF REUSE		581. REUSE			
582. DATE OF REPAIR		583. REPAIR			
584. DATE OF REPLACEMENT		585. REPLACEMENT			
586. DATE OF REMOVAL		587. REMOVAL			
588. DATE OF REUSE		589. REUSE			
590. DATE OF REPAIR		591. REPAIR			
592. DATE OF REPLACEMENT		593. REPLACEMENT			
594. DATE OF REMOVAL		595. REMOVAL			
596. DATE OF REUSE		597. REUSE			
598. DATE OF REPAIR		599. REPAIR			
600. DATE OF REPLACEMENT		601. REPLACEMENT			
602. DATE OF REMOVAL		603. REMOVAL			
604. DATE OF REUSE		605. REUSE			
606. DATE OF REPAIR		607. REPAIR			
608. DATE OF REPLACEMENT		609. REPLACEMENT			
610. DATE OF REMOVAL		611. REMOVAL			
612. DATE OF REUSE		613. REUSE			
614. DATE OF REPAIR		615. REPAIR			
616. DATE OF REPLACEMENT		617. REPLACEMENT			
618. DATE OF REMOVAL		619. REMOVAL			
620. DATE OF REUSE		621. REUSE			
622. DATE OF REPAIR		623. REPAIR			



1. TITLE		2. DATE	
3. AUTHOR		4. PROJECT	
5. SUBJECT		6. LOCATION	
7. (28) Area west of Hernandez			
8. w p			
9. APPROVED BY		10. REVIEWED BY	
11. CLASSIFICATION			
12. DISTRIBUTION		13. COMMENTS	
FORM NO. 60-53 SEP 1948			
CAPTION REPORT			



1. AREA OF INTEREST		2. DATE	
3. AREA OF INTEREST		4. DATE	
5. AREA OF INTEREST		6. DATE	
7. TITLE			
(29) Area west of Hernandez			
wps			
8. DATE OF PHOTO		9. DATE OF PHOTO	
10. CLASSIFICATION			
11. CAPTION REPORT			

Approved For Release 2000/09/11 : CIA-RDP80-00809A000500450279-1


30 negs for
4x6 work prints
to be numbered to
correspond to numbers
on negatives —

25X1A



NOT
SUITABLE
FOR
MICROFILE

25X1A



ATTS: 2 MAPS

HARD COPY

ON FILE